

iv) Means of Escape (a-):

Sl. No.	No. of stair cases	Width of meters	Total Width
1	Internal 1 No.	03.25	03.25 meters
2	External 2 Nos.	01.50	03.00 meters

(b)

Highest No. of Students in a floor	Width of Stair cases required (No. of students divided by 50 Meters)	Aggregate width of Staircases provided	Deficit
300	300/50 = 06.00 meters	06.25 meters	Nil

v) Fire Safety Measures:

Sl. No.	Fire Safety Measures	Required as per Table 23 of NBC of India, 2005	Provided	Deficiency
1	Fire Extinguishers & Buckets	48 Nos. & 48 Nos.	48 Nos. & 48 Nos.	Nil
2	Hose Reel	9 Nos	9 Nos	Nil
3	Automatic Sprinkler system in basement if area of basement exceeds 200 Sq. meters	N.A	N.A	Nil
4	a) Terrace Tank capacity 5,000 Lts. b) Additional 5000 liters if area of basement exceeds 200 sq. meters.	10,000 Lts.	10,000 Lts.	Nil
5	a) One Booster pump of 450 LPM b) One booster pump of 900 LPM if basement area exceeding 200 M2	900 LPM	900 LPM	Nil

vi) Additional Fire safety measures in lieu of deficiency in open spaces provided as per G.O.Ms.

No 154 M.A. & U.D Dept., dt. 13-03-2007 and Memo. No.4011/M1/2008. M.A. & U.D Dept., dt.19-05-2008.

Sl No.	Safety Measure	Required	Provided	Deficiencies
1	NA	NA	NA	NA

4) The existing building NRI's INDIAN SPRINGS E.M. SCHOOL ,Tenali town Guntur

District. is provided with Fire safety measures prescribed in Part 4, NBC-05, and could not follow completely G.O.Ms.No.154, M.A. & U.D Dept., dated 13-03-2007 and Memo. No. 4011/M1/2008, M.A. & U.D Dept., dated 19-05-2008 and the committee recommended after providing the above possible additional Fire Safety measures.

5)The Fire safety systems were tested by the committee members during the inspection and Performance found satisfactory. Therefore, this office has No Objection for Occupancy Clearance to the existing Educational Building NRI's INDIAN SPRINGS E.M. SCHOOL ,Tenali town Guntur District. subject to the following conditions.

I	All the fire protection arrangements shall be maintained in good repair as seen during inspection.
II	All the escape / exit routes shall not be kept locked / blocked or encroached.
III	All the occupants must know the correct method of operation of the fire fighting system installed
IV	Any loss of life or property due to non-functioning of fire safety and other installations shall be the responsibility of the management.
V	All students / staff members of the institution shall be trained to operate the fire safety equipments during emergency.
VI	Addition / alteration, if any in the building may be obtained with prior permission from this Dept..
VII	Mock drills should be conducted once in 3 months for initial two years. Thereafter once in every 6 months

6) This occupancy clearance is valid for a period of one year from the date of issue.

Yours faithfully,

District Fire Officer,
Guntur

Copies to the

- Correspondent, NRI's INDIAN SPRINGS E.M. SCHOOL ,Tenali Guntur District.
- Station Fire Officer, Tenali.
- Asst. District Fire Officer, Guntur.
- Regional Joint Director, Educational Department, Guntur.
- Copy submitted Regional Fire Officer, S.R., Hyderabad for information.